



Report Number: QIP-ASR1541342

Audit Date : 10 Dec., 2015

This report is issued by Focus Technology Co., Ltd. (Made-in-China.com) and the supervising inspectorate (SGS-CSTC Standards Technical Services Co., Ltd.) to confirm that:

Company Name : Nanjing Haisi Extrusion Equipment Co., Ltd.

南京海思挤出设备有限公司

Showroom: http://hsextruder.en.made-in-china.com/

Address : No. 7, Zhongxing East Road, Lishui Development Zone, Nanjing,

Jiangsu, China

Product : Twin Screw Extruder

has been on site audited for the Following Scope of Activity

1. General Information

- 2. Management System and Product Certification
- 3. Production Capacity & Quality Control

4. Photos



General Comments:

Nanjing Haisi Extrusion Equipment Co., Ltd. is a manufacturer with 55 employees; it was established in 2008, located in No. 7, Zhongxing East Road, Lishui Development Zone, Nanjing, Jiangsu, China. The buildings occupy an area of more than 5,230 square meters. They have obtained CE certificate for twin screw extruder pelletizing lines.

Sign for and on behalf of

SGS-CSTC Standards Technical Services Co., Ltd.



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions. aspx Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN Doccheck@sss.com







SUPPLIER ASSESSMENT REPORT

Audited Company	Nanjing Haisi Extrusion Equipment Co., Ltd.	
Audited Site:	No. 7, Zhongxing East Road, Lishui Development Zone, Nanjing, Jiangsu, China	

Consigner of Assessment	Made-in-China.com		
Audit Type	☐ Initial Audit		THE PERSON NAMED IN
	□ Re-audit		E RATICIO TARGESTA
Audit Date	10 Dec., 2015	Verify Report	www.sgs.com/ecv
Auditor	Mr. Simon Gao	Reviewed by	Mr. Simon Wang

CONTENTS

\boxtimes	Part A:	General	In	forma	tion
-------------	---------	---------	----	-------	------

Section 1: Company Overview

Section 2: Human Resources

Part B: Foreign Trade Capacity

Section 1: Export Overall Situation

Section 2: Export Business Capacity Section 3: Supplier Management

Section 4: After-sales Service Capacity

Part C: Product Research & Development Capacity

Section 1: Product Research & Development Capacity

Part D: Management System and Product Certification

Section 1: Management System(s) and Product Certification

□ Part E: Production Capacity & Quality Control

Section 1: Production Capacity Section

Section 2: Production Process Control

Part F: Financial Position

Section 1: Financial Data

Section 2: Key Performance Indications

Section 3: Banking

Section 4: Product Insurance

Part G: Working Environment

Section 1: Working Environment

Part H: Energy Saving and Emission Reduction

Section 1: Environmental Management

Section 2: Water, Gas and Noise Control

Part I: Industry Information

Section 1: Industry Information

Part J: Photos

Section 1: Photos of Documents

Section 2: Photos of Company



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions., aspx Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Page No : 2 of 11

Page No.: 2 of 11

5/F, B-4 Building, Zijin (Baixia) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China 210014 t (86-25) 87128385 f (86-25) 83407773 中国・南京・秦淮区光华路1号紫金白下创业特别社区4号楼B幢5楼 邮编: 210014 t (86-25) 87128385 f (86-25) 83407773

e as.cn@sgs.com





Part A: General Information

Section 1: Company Overview

1.1 Legal Validity				
Does the company have a valid business license?		Registration Number	320104000081017	
Year of established	05 Nov., 2008	Valid Date	04 Nov., 2028	
Registered address	No. 2, Hewan, Qiqiao Village, Qinh	uai District, Nanjing C	ity	
Actual address	No. 7, Zhongxing East Road, Lishu	i Development Zone,	Nanjing, Jiangsu, China	
Does the company in abnormal operation status list of industrial and commercial bureau?	No			
Registered capital	RMB 800,000			
Name of legal representative	Mr. Kai Ding			
Business scope	Manufacture and sales of mechanical equipment and plastic extruding equipment; Sales of hardware, mechanical and electric products. (any project that needs to be approved by law can only be carried out after getting approval by relevant authorities)			
1.2 Basic Information				
Contact person	Mr. Zhou			
Phone number	0086-13852327847	Fax number 00	86-25-52657507	
URL/Web address	http://www.hsextruder.com			
Company type				
Type of ownership	 ☐ Limited Company ☐ Public Company ☐ Foreign joint venture ☐ State-Owned ☐ Private Owner ☐ Wholly foreign-owned enterprises 			
Subsidiary company	■ Company name: Nanjing Haisi Extrusion Equipment Co., Ltd. ■ Company name: Nanjing Kairong Machinery Technology Co., Ltd. (南京凯荣机电科技有限公司) ■ The relationship of two companies: □ The two companies have the same legal representative □ One company has more than 20% of the shares of another company			
Products manufactured / sold scope	Twin Screw Extruder			
1.3 Company Building Information				
According to: Land certificate Real estate certificate Lease agreement Observation Estimated on site The company area 5,232.12 square meters The land occupies square meters. Not provided The offices occupy 1,000 square meters.				
The workshops occupy 4,200 square meters.				



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions. aspx Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


Page No.: 3 of 11

Page No.: 3 of 11

5/F, B-4 Building, Zijin (Baixia) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China 210014 t (86-25) 87128385 f (86-25) 83407773 www.sgsgroup.com.cn 中国·南京·秦淮区光华路1号紫金白下创业特别社区4号楼B幢5楼 邮编: 210014 t (86-25)87128385 f (86-25)83407773 e as.cn@sgs.com



Section 2: Human Resources



2.2 Explanation of Code and Employee Details			
Code	Department	Number of employees	
Α	General Manager	1	
В	Financial Dept.	5	
С	Admin Dept.	1	
D	Sales Dept.	10	
E	Technology and Quality Control Dept.	5	
F	Production Dept.	31	
G	Warehouse	2	
	Number in total:	55	

2.3 Key Staff Working experience for this trade / Full name Title **Education** total experience Not provided Not provided Not provided Not provided



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions., aspx Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Page No.: 4 of 11

Page No.: 4 of 11

5/F, B-4 Building, Zijin (Baixia) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China 210014 t (86-25) 87128385 f (86-25) 83407773 中国・南京・秦淮区光华路1号紫金白下创业特别社区4号楼B幢5楼 邮编: 210014

t (86-25) 87128385 f (86-25) 83407773

www.sgsgroup.com.cn e as.cn@sgs.com





Part D: Management System and Product Certification

1.1 Management System and Product Certification			
Management system certification	☐ ISO9001:2008 certificate		
	☐ ISO14001:2004 certificate		
	☐ OHSAS18001:2007 certificate		
	☐ TS16949		
	☐ SA8000		
	☐ Others		
	⊠ NIL		
Product certification	□ CE NO.: 2026130212 Product Name: Twin screw extruder pelletizing lines Model: TSE-75, TSE-135, TSE-95, TSE-68, TSE-65, TSE-60, TSE-52, TSE-40, TSE-35, TSE-30 and TSE-20 Standard: Directive 2006/42/EC and 2006/95/EC Issued by: Safenet Limited Issue Date: 16 Feb., 2012		
	□ UL		
	□ ccc		
	☐ RoHS		
	□ FCC		
	☐ Others		
	□ NIL		
Test reports for raw materials	□ RoHS		
	Reach		
	☐ Others		
	⊠ NIL		



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions. aspx Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Page No.: 5 of 11

Page No.: 5 of 11

5/F, B-4 Building, Zijin (Baixia) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China 210014 t (86-25) 87128385 f (86-25) 83407773 www.sgsgroup.com.cn 中国·南京·秦淮区光华路1号紫金白下创业特别社区4号楼B幢5楼 邮编: 210014 t (86-25)87128385 f (86-25)83407773 e as.cn@sgs.com





Part E: Production Capacity & Quality Control

Section 1: Production Capacity





This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions. aspx Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction forom exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Page No : 6 of 11

Page No.: 6 of 11

5/F, B-4 Building, Zijin (Baixia) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China 210014 t (86-25) 87128385 f (86-25) 83407773 中国・南京・秦淮区光华路1号紫金白下创业特别社区4号楼B幢5楼 邮编: 210014 t (86-25) 87128385 f (86-25) 83407773 e as.cn@sgs.com



SGS No: QIP-ASR1541342



Connecting Buyers with Chinese Suppliers

	Lathe	China	N/A	10
	Milling machine	China	N/A	3
	Vertical milling machine	China	N/A	2
	Grinding machine	China	N/A	3
	Vertical drilling machine	China	N/A	2
	Radial drill	China	N/A	4
	Drying equipment	China	N/A	1
62/232	Sawing machine	China	N/A	2



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions. aspx Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN_Doccheck@sgs.com Page No.: 7 of 11

5/F, B-4 Building, Zijin (Baixia) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China 210014 t (86-25) 87128385 f (86-25) 83407773 www.sgsgroup.com.cn 中国·南京·秦淮区光华路1号紫金白下创业特别社区4号楼B幅5楼 邮编: 210014 t (86-25)87128385 f (86-25)83407773 e as.cn@sgs.com



Section 2: Production Process Control

2.1 Production Process Control				
Item	Content	Observations /Comments		
1	Product R&D capacity	☐ Own brand☑ ODM☑ OEM		
2	Are the environmental conditions, such as tidiness and cleanliness being controlled and suitable for the operation performed?	□ Very tidy☑ Normal□ Need to improve□ Very poor		
3	Are the necessary items /documents provided at appropriate location and under control?	 ☐ Work Instructions /procedures ☑ Workmanship standard /acceptance ☐ Golden sample /Approval sample ☐ Product picture ☐ Verbal by workshop director 		
4	Are written instructions available for incoming material inspections /testing? Is the relevant record maintained?	 ☐ Has instructions and uniformly followed ☐ Has instruction but no written records ☒ Materials checked by storage staff 		
5	Are written inspections /testing instructions available for finished products? Is the relevant record maintained?	☑ Have instructions and uniformly followed☐ Have instruction but no written records☐ Finished product checked by packing staff		
6	What type of inspection is used for finished products?	 □ Random inspection □ Visual inspection □ Function inspection ☑ 100% inspection ☑ Visual inspection ☑ Function inspection 		
7	Are non-conforming units clearly marked/ segregated to prevent accidental dispatch?	☐ Marked and segregated☐ Segregated but not marked clearly☒ Not found on site		
8	How are the non-conforming units handled?	☑ Repaired and re-inspection☐ Picked out☐ Used under control☐ Others		



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions. aspx Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction forom exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Page No.: 8 of 11

Page No.: 8 of 11

5/F, B-4 Building, Zijin (Baixia) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China 210014 t (86-25) 87128385 f (86-25) 83407773 www.sgsgroup.com.cn 中国·南京·秦淮区光华路1号紫金白下创业特别社区4号楼B幅5楼 邮编: 210014 t (86-25)87128385 f (86-25)83407773 e as.cn@sgs.com




Part J: Photos

Section 1: Photos of Documents

Description: Business License



Description: Lease Agreement



Description: Tax Registration License



Description: Lease Agreement





This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions., aspx Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Page No.: 9 of 11

Page No.: 9 of 11

5/F, B-4 Building, Zijin (Baixia) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China 210014 t (86-25) 87128385 f (86-25) 83407773 中国·南京·秦淮区光华路1号紫金白下创业特别社区4号楼B幢5楼 邮编: 210014 t (86-25) 87128385 f (86-25) 83407773 e as.cn@sgs.com





Section 2: Photos of Company

Description: Company Building



Description: Office Entrance



Description: Office



Description: Company Building



Description: Showroom



Description: Meeting Room





This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx.Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.


Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Page No - 10 of 11

Page No.: 10 of 11

5/F, B-4 Building, Zijin (Baixia) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China 210014 t (86-25) 87128385 f (86-25) 83407773 中国·南京·秦淮区光华路1号紫金白下创业特别社区4号楼B幢5楼 邮编: 210014 t (86-25)87128385 f (86-25)83407773

e as.cn@sgs.com





ade-in-China.com

Connecting Buyers with Chinese Suppliers

Description: Workshop

SGS



Description: Workshop



Description: Workshop

Description: Equipment



Description: Finished Products



Description: Finished Products



-- End of the Report --



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions. aspx Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction forom exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Page No.: 11 of 11

Page No.: 11 of 11

5/F, B-4 Building, Zijin (Baixia) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China 210014 中国・南京・秦淮区光华路1号紫金白下创业特别社区4号楼B幢5楼 邮编: 210014

t (86-25) 87128385 f (86-25) 83407773 t (86-25) 87128385 f (86-25) 83407773

e as.cn@sgs.com